





(Document Name) Drawing
(Fig. 1)




(Fig. 2)







(Fig. 3)




(Fig. 4)






(Fig. 6)


NOZZLE No.	COORDINATE		PULSE 1	PULSE 2	-----	PULSE n
	x	y				
1						
2						
3						
⋮						
3584						




(Fig. 7)



(Fig. 8)



(Fig. 9)









Fig. 10)





(Fig. 11)







(Fig. 12)



(Fig. 13)




(Fig. 14)






(Fig. 15)



(Fig. 16)





NOZZLE No.	COORDINATE		PULSE 1	PULSE 2	-----	PULSE n
	x	y				
n1			07e0			
n2			03e0			
n3			03c0			

(Fig. 18)


NOZZLE No.	COORDINATE		PULSE 1	PULSE 2	-----	PULSE n
	x	y				
n1			03c0			
n2			0340			
n3			02c0			

(Fig. 19)





(Fig. 20)



(Fig. 21)

